Agilent Technologies Inc.
2850 Centerville Road
Wilmington DE 19808-1610
United States

Tel. 800 227 9770 Option 3, 1 7648#
Fax: 1-302-993-5963
Email: soclosurerequest@agilent.com
Website: www.agilent.com/chem

Customer Contact:
County of Brazoria
PO Box 817
ANGLETON TX 77516-0817
USA

TAX ID :

Melissa Henry
MHenry@brazoriacountytx.gov
9798642271

Invoice To:
County of Brazoria
PO Box 817
ANGLETON TX 77516-0817
USA

Payer:
County of Brazoria
237 E Locust St
ANGLETON TX 77515-4621
USA
County of Brazoria

Delivery Site:
County of Brazoria
Sheriff's Office
3602 County Road 45
ANGLETON TX 77515-9575
USA

Location:
Room
Bldg
Lab
Dept

SERVICE REPORT

Customer Purchase Order Number:	**Customer Number:** 70013483
Service Request:	**Service Request Date:**
Service Order: 6007326655	**Service Confirmation:** 6906109757

Direct Inquiries to:

Contact Name:	Customer Contact Center
Contact E-mail:	soclosurerequest@agilent.com
Contact Telephone:	800 227 9770 Option 3, 1 7648#
Contact Fax:	1-302-993-5963

products | applications | software | services

Learn more about Agilent's Special Offers, Products, Services and our full range of laboratory productivity solutions optimized for your applications and workflows. Visit us at www.agilent.com/chem

Agilent Technologies Inc
5301 Stevens Creek Blvd
Santa Clara CA 95051
United States

Federal Tax ID: 77-0518772

Beneficiary Bank: Bank of America
SWIFT: BOFAUS3N
Beneficiary Account: 12331-31561
Beneficiary Name: Agilent Technologies Inc

ORIGINAL

Service Instrument:


Model Number	Model Description	Serial Number	System Handle	Parent Asset
SYS-GC-7890-E	GC 7890 System Enhanced GC Features		TOXICOLOGY BAC2	
G3445B	7890 Series GC for Analyzers	US13263029	TOXICOLOGY BAC2	SYS-GC-7890-E
G4557A	7697A Headspace Sampler, 111 Vial	CN16210024	TOXICOLOGY BAC2	SYS-GC-7890-E

Service Items:

Item	Service/Part #	Description	Qty	Entitlement	Service Start	Service End
1000	PM	Preventive Maintenance	1.00	Agreement Entitlement - 100 % covered	01/23/2025	01/23/2025
1010	19231-60680	Ignitor Glow Plug Assembly	2.00	Agreement Entitlement - 100 % covered		
1020	0100-2594	Fitting-internal Reducer 1/16 to 1/32-in	2.00	Agreement Entitlement - 100 % covered		
1030	5181-8818	Liner, direct, 2mm ID, deactivated	2.00	Agreement Entitlement - 100 % covered		
1040	G3530-00610	Thermal Gap Insulation Foam	1.00	Agreement Entitlement - 100 % covered		
1050	G4556-63825	7697A Sample Probe, Deactivated	2.00	Agreement Entitlement - 100 % covered		
1060	G4556-80106	Sample loop, Headspace 1.00 ml, inert	1.00	Agreement Entitlement - 100 % covered		
1070	G4556-80108	Sample Loop, Headspace 3.00 ml, inert	1.00	Agreement Entitlement - 100 % covered		
1080	5188-5365	Liner O-Ring, Non-Stick 10PK	1.00	Agreement Entitlement - 100 % covered		
1090	5188-5367	Gold Plated Inlet Seal with Washer	1.00	Agreement Entitlement - 100 % covered		
1100	5188-6495	Split vent trap PM kit,single cartridge	1.00	Agreement Entitlement - 100 % covered		
1110	G1531-80560	Jet, Capillary Optimized,0.29mm ID	2.00	Agreement Entitlement - 100 % covered		

Additional Information:

Service Information:

Problem Description: JJan25,PM,SYS-GC-7890-E,TOXICOLOGY BAC2#		
Service Provided: PM Completed Per Checklist. Replaced S/SL Inlet Septa, Liner (HS), Gold Seal, & Split Vent Trap. Replaced Front & Back FID Jets (0.011) & Ignitor Assy. Replaced Headspace Sample Probe, Sample Loop (1mL), & Transfer Line (Pro Steel). Intermittent Jerking Motion & Noise Coming From Gripper Assy.		
Service Overview Code: Reason Code: Scheduled Service Diagnosis Code: Scheduled Service Resolution Code: Scheduled Service		
Reported Hours: 4.0	**Travel Hours:** 0.0	
Customer Field Service Representative Name: **Brian Cunningham**	**Customer Field Service Representative Signature:** 	**Date:** **23 Jan 2025**
Customer Name:	**Customer Signature:**	**Date:**
Additional Comments:		